

TE Connectivity

Product Change Notification: E-19-002279

PCN Date: 25-APR-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Spirap. Continuous spirally cut tube for binding wires and cable

Description of Changes

Wall thickness reduction, and increase in helical cut pitch. The change affects seven parts only.

Reason for Changes:

Product Improvement. Process tooling was changed during 2017. Product will be lighter, and require less wrapping during installation. Customer should confirm suitability before use.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

29-MAY-2019

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
142830-2	NO		"AMP-0-0142830-2", "D87753-000"			
142831-1	NO		"AMP-0-0142831-1", "C28110-000"			
142835-2	NO		"CN8562-000", "SIML-0-0142835-2"			
142839-4	NO					
142840-2	NO		"D03854-000", "AMPS-0-0142840-2"			
142841-1	NO					

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

Drawing Number	Current Revision	New Revision
142831	A	